

Field Note Record

| Contract No. Station | | Mile/Line: | | C/S | C/S | | | |
|----------------------|------------|-------------------|------|---------------|---------------------|--|--|--|
| 009359 | Section 4A | US-12 | | | | | | |
| Staked by | Date | Work Started Date | | Work Complete | Work Completed Date | | | |
| SURVEY | | 7/8/2019 | | | | | | |
| 7/1/2019 | | | | | | | | |
| Calculated by | / Date | Checked by | Date | Inspector | Date | | | |
| Scott Busby | | E. Knudson | | Scott Busby | 8/5/19 | | | |
| 8/5/2019 | | 8/8/2019 | | | | | | |

Section 1 - I-90, MP 33.44 to MP 136.43 EAM GUARDRAIL TYPE 31

Est.#5

Group Number 1

7/22/2019 - I-90

- Station MP 33.48 Main RT WB Sheet 3 Install 175 LF of Beam Guardrail Type 31
- 175 37.5 = 37.5 (6 posts) + (137.5/6.25 = 22) Total of **28** wood posts
- 8 steel post (Typ.)

Group Number 2

7/22/2019 - I-90

- Station MP 35.43 Main RT WB Sheet 1 Install 37.5 LF of Beam Guardrail Type 31
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)

Group Number 8

7/29/2019 - I-90

- Station MP 83.45 Main LT EB Sheet 2 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)
- Station MP 85.84 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)
- Station MP 95.97 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)

7/30/2019 - I-90

- Station MP 85.84 Main LT EB Sheet 4 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)
- Station MP 96.86 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type

- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)

7/31/2019 - I-90

- Station MP 97.23 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)
- Station MP 100.52 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood post
- 8 steel post (Typ.)
- Station MP 101.04 Main RT EB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood post
- 8 steel post (Typ.)

8/1/2019 - I-90

- Station MP 110.13 S1 Ramp 110 on ramp 0.57 LT WB Sheet 3 Install 237.5 LF of Beam Guardrail Type 31
- 237.5 37.5 = 37.5 (6 posts) + (200/6.25 = 12) Total of **38** wood posts
- 8 steel post (Typ.)

8/2/2019 - I-90

- Station MP 96.96 Main LT WB Sheet 1 Install 37.5 LF of Beam Guardrail Type
- 37.5 = (6 posts) Total of **6** wood posts
- 8 steel post (Typ.)

```
Sub Total: ((37.5*9)+237.5) = 575 LF

((6*9)+38) = 92 EA - Wood Posts

((8*10) = 80 EA - Steel Posts
```

Group Number 9

7/30/2019 - I-90

- Station MP 84.19 Main RT EB Sheet 2 Install 37.5 LF of Beam Guardrail Type 31
- 37.5 (6 posts) for a total of **6** wood posts
- 8 steel posts

8/2/2019 - I-90

- Station MP 83.91 Main RT WB Sheet 2 Install 37.5 LF of Beam Guardrail Type 31
- 37.5 (6 posts) for a total of 6 wood posts
- 8 steel posts

Group Number 10

8/1/2019 - I-90

- Station MP 106.33 R1 Ramp 106 off ramp 0.17 LT WB Sheet 2 Install **37.5 LF** of Beam Guardrail Type 37
- 37.5 (6 posts) for a total of **6** wood posts
- 8 steel posts

Total: (175+37.5+575+75+37.5) = **900 LF** (28+6+92+6) = **132 EA** - Wood Posts (8+8+80+16+8) = **120 EA** - Steel Posts

Note:

Measured by wheel and counted

| Item Num | Material Brand Name/Model Type | Man | Manufacturer | | Brand Name/Mo | odel Type | RAMS/QPL Ref. No. | . Appr/Ad Code | c Bas | Basis of Accept | |
|-------------|---|-----|----------------------------------|------|------------------|--------------------|-------------------------|-------------------|--|--|-------------|
| 015.02 | Beam Guardrail Thrie Beam Elements and Components | | Trinity Highway Products, LLC | | | QPL-0001 | | 2215 | / Mfr. Cert. per Stnd. Spec. 1-06.3 | | itnd. |
| 015.03 | Beam Guardrail Wood Pos and Blocks | | | | | QPL-0005 | | 2550 | or G and Trea Env | V Lumber Grading Stamp or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09.3 (1) Applies) V Mfr. Cert. per Stnd. Spec. 1-06.3 | |
| 015.04 | Beam Guardrail Steel Post and Blocks | | Trinity Highway Products, LLC` | | | | | 2215 | | | |
| Item Num | Item Description | Grp | Date Work Complete | Unit | Quantity | Ledger Entry No | Posted By D. Init. Date | | Che Init. | cked By Date | Est. No. |
| 0015 | BEAM GUARDRAIL TYPE 31 | 1 | 8/5/2019 | L.F. | 175 | 177 | EK | 08/09/19 | | | 5 |
| 0015 | BEAM GUARDRAIL TYPE 31 | 2 | 8/5/2019 | L.F. | 37.5 | 178 | EK | 08/09/19 | | | 5 |
| 0015 | BEAM GUARDRAIL TYPE 31 | 8 | 8/5/2019 | L.F. | 575 | 179 | EK | 08/09/19 | | | 5 |
| 0015 | BEAM GUARDRAIL TYPE 31 | 9 | 8/6/2019 | L.F. | 75 | 180 | EK | 08/09/19 | | | 5 |
| 0015 | BEAM GUARDRAIL TYPE 31 | 10 | 8/5/2019 | L.F. | 37.5 | 181 | EK | 08/09/19 | | | 5 |

Attachments



Things to do 82-2.xlsx Microsoft Excel Worksheet 400 KB

DOT Form IP 422-635ER EF Revised 4/2009